


# Commercial Baseline Study: Where are we?

Nigel Makela




# Where is the data coming from

- Colorado
- Florida
- Utah
- Washington D.C
- Idaho
- Nebraska



## Building Envelope

The background of the slide is a photograph of a multi-story building under construction. The building is covered in scaffolding, and the facade is a mix of concrete and brickwork. The sky is clear and blue.

In the field, insulation generally met or exceeded requirements for prescriptive approach.

No NFRC Certificates for site built windows

Insulation values sometimes called out on plans



## Lighting

Lack of compliance with daylighting controls

Bi-level switching was mostly fulfilled with occupancy sensors

The background image shows a rooftop HVAC system with several white condenser coils and metal grilles. A red rounded rectangle is in the top left, and two white rounded rectangles with red borders are in the center and bottom right, containing text.

## HVAC

Always had an economizer where needed.

Good compliance with insulating and sealing ductwork and thermostatic controls

# Lack of Documentation

Lighting  
Compliance

Envelope  
compliance

HVAC compliance

# Questions?

